



Project Description

Project Title	CSR Maintenance & Well 46 Repair 2024
Project Location GPS coords, street address or location name	Canning Stock Route entire length starting at northern end
Dates	Leave Perth Aug 6 for approx. 5-6 weeks
Project Description	Conduct annual maintenance of toilets, camps sites, fire control & paint directional signs. Repair Well 46 fire damage Ranger sign at Whispering Pines (near Well 49) Repair toilet trolley at Well 49 Install new signs at Newman, Halls Creek & Wiluna
Project Leader	Rod Durston
TCWA Members	Yes
Other Club?	Yes


Tasks Required on Project
Well 46 was partially burnt out 2 years ago and the top 3 levels of well liners, the top platform and steel lids need replacing
Ngurrara Rangers want to erect information sign at Well 49 Whispering Pines
Maintenance – Clear Buffel & spinifex from near toilets, empty toilets, replace lime/ash & general cleanout
Repaint directional and well no. signs, General tidy up of camp areas
Repair tyre at Well 49 & Durba Springs
1 x TCWA trailer needs to be towed by someone.

Equipment	Personal
Extensive TCWA tool kit & trailers will be taken	
Racks, Mattocks, shovels	
Sleepers & Well lids	

Funded by	Amount
Self	



Location diagram





Well 46 Repair

Other maintenance items

1. Cleanout all toilets
2. Remove vegetation around toilets and restored wells for fire prevention
3. Paint all directional & well signs
4. Repair trailer wheel at Well 49
5. Repair trailer wheel at Durba Springs
6. Pump out wells to refresh water (if required)
7. Evaluate reconstruction of toilet at Lake Stretch
8. Install visitor signs at Newman, Halls Creek & Wiluna
9. Repair fences, bollards etc at wells
10. Survey area around Lake Disappointment for possible campsite
11. Historic CSR scrapper to be reinstated near top end of CSR TBA.
12. Evaluate Well 33 windmill for proper operation
13. Remove any rubbish
14. Measure water levels of wells